

FILE 'HCAPLUS' ENTERED AT 13:22:59 ON 29 NOV 2004

E SURFACE ROUGHNESS/CT

L1 19740 S "SURFACE ROUGHNESS"/CT OR ("INTERFACE ROUGHNESS"/CT OR "SURFACE SMOOTHNESS"/CT)

FILE 'REGISTRY' ENTERED AT 13:24:06 ON 29 NOV 2004

L2 90 S O.PR/MF OR O PR/ELF

FILE 'HCAPLUS' ENTERED AT 13:24:16 ON 29 NOV 2004

L3 4542 S L2
L4 4542 S L2 AND L3
L5 0 S L4 AND NANOROUGH#####
L6 216 S L4 AND (INTERFAC##### OR BODY)
L7 0 S L6 AND ULTRASMOOTH?
L8 0 S L6 AND ULTRA SMOOTH?
L9 27 S L4 AND "LESS THAN"
L10 63 S L4 AND NANO#####
L11 166 S L4 AND NM
L12 1 S L9 AND (L10 OR L11)
L13 12 S L6 AND (L9 OR L10 OR L11)
L14 12 S L13 NOT L12
L15 210 S ULTRA SMOOTH##### OR ULTRASMOOTH#####
L16 0 S BODY(5A) (REGION OR INTERFAC#####) AND L15
L17 0 S (REGION(5A) INTERFAC#####) AND L15
L18 2982 S (NM OR NANO#####) (3A) ROUGH#####
L19 1 S L2 AND L18
L20 4 S L2 (L) (SMOOTH##### OR ROUGHNESS)
L21 272 S L2 (L) (DIELEC##### OR INSULAT##### OR KAPPA)
L22 5 S L21 AND L1
L24 3 S L22 NOT (L20 OR L19 OR L14 OR L12)
L25 974 S BODY REGION
L26 0 S L25 AND (SMOOTH##### OR ROUGH#####) (4A
) INTERFAC#####
L27 7 S L25 AND (SMOOTH##### OR ROUGH#####)
L28 7 S L27 NOT (L24 OR L20 OR L19 OR L14 OR L12)
L29 0 S GATE OXIDE AND L28
L30 0 S DIELEC##### AND L28

FILE 'INSPEC' ENTERED AT 13:51:41 ON 29 NOV 2004

E SURFACE ROUGHNESS/CT

L31 33801 S ("SURFACE TOPOGRAPHY"/CT OR "SURFACE ROUGHNESS"/CT) OR "SURFACE TOPOGRAPHY"/CT OR "INTERFACE ROUGHNESS"/CT
L32 1644 S "INTERFACE ROUGHNESS"/CT
L33 0 S L32 AND PRO/CHI
L34 0 S L32 AND PR2O3/CHI
L35 1 S L31 AND PR2O3/CHI
L36 268 S PR2O3
L37 2 S (L31 OR L32) AND L36
L38 1 S L37 NOT L35
L39 108 S SURFACE ROUGHNESS AND GATE OXIDE
L40 0 S SURFACE ROUGHNESS AND BODY REGION
L41 42 S (L39 OR L40) AND INTERFAC#####
L42 0 S L41 AND BODY
L43 0 S L41 AND PR/CHI
L44 0 S L41 AND ULTRASMOOTH?
L45 0 S L41 AND ULTRA SMOOTH?
L46 7 S L41 AND SMOOTH?